




Схемы соединений



Обозначение	НСХ	L, мм	Масса, г, не более
ТСМ.ГПКШ.035	50M	150	20
-01	50M	1000	35
-02	50M	1600	50
-03	50M	800	30
-04	50M	1000	40
-05	50M	1620	55
-06	50M	3000	85
-07	50M	4000	120
-08	50M	5000	160
-10	100M	150	20
-11	100M	1000	35
-12	100M	1600	50
-13	100M	800	30
-14	100M	1000	40
-15	100M	1620	55
-16	100M	3000	85
-17	100M	4000	120
-18	100M	5000	160