




Схемы соединений



Обозначение	НСХ	L, мм	d, мм	Масса, г, не более
ТСМ.ГПКШ.038	50M	120	8	360
- 01	50M	160	8	380
- 02	50M	200	8	410
- 03	50M	250	8	440
- 04	50M	320	8	410
- 05	50M	400	8	580
- 06	50M	500	10	630
- 07	50M	630	8	690
- 08	50M	800	8	770
- 09	50M	1000	10	840
- 10	50M	1250	10	960
- 11	50M	1500	10	1100
- 12	50M	1600	10	1120
- 13	50M	2000	10	1320
- 14	50M	2500	10	1570
- 15	50M	3250	10	1900
- 16	50M	800	10	770
- 20	100M	120	8	360
- 21	100M	160	8	380
- 22	100M	200	8	410
- 23	100M	250	8	440
- 24	100M	320	8	410
- 25	100M	400	8	580
- 26	100M	500	10	630
- 27	100M	630	8	690
- 28	100M	800	8	770
- 29	100M	1000	10	840
- 30	100M	1250	10	960
- 31	100M	1500	10	1100
- 32	100M	1600	10	1120
- 33	100M	2000	10	1320
- 34	100M	2500	10	1570
- 35	100M	3250	10	1900
- 36	100M	800	10	770
-37	50M	120	10	360
-38	50M	160	10	380
-39	50M	400	10	580
-40	50M	630	10	690
-41	50M	320	10	410